Illinois Division CLIC Bulletin No. 1

# THE ATCHISON, TOPEKA and SANTA FE RAILWAY COMPANY



CAR LOCATION and INVENTORY CONTROL FT. MADISON, IOWA

Issue Date: March 20, 1973


E. O. Chaddock Supt. Ft. Madison, Iowa

#### INTRODUCTION

This booklet contains instructions and maps concerning the Santa Fe CAR LOCATION INVENTORY CONTROL (CLIC) System for all locations referred to as "BLIND SIDINGS" that come within the Ft. Madison, Iowa area of responsibility. These locations are as follows:

Wyaconda, Mo.
Argyle, Mo.
Revere, Mo.
Medill, Mo.
Gorin, Mo.
Rutledge, Mo.
Niota, Ill.
Dallas City, Ill.
Lomax, Ill.

A Zone number has been assigned to each of the above locations. Each track at these locations and each spot on each track has also been assigned a number. These number combined will contain six digits designated as the ZONE, TRACK and SPOT numbers. Example:



The following General Instructions set forth instructions for all Trainmen who will be performing work at any of the above locations.

#### GENERAL INSTRUCTIONS

5 .....

In order to obtain current and correct information to enable the Santa Fe to maintain correct Demurrage records and facilitate handling loaded and empty cars in a more expedient manner, the following instructions must be adhered to without fail:

(1) LOADS AND EMPTIES FROM FT. MADISON DESTINED TO BLIND SIDINGS WITHIN FT. MADISON AREA OF RESPONSIBILITY - Trainmen will be furnished a

list indicating the CLIC number each car will be spotted to. Trainmen will endeavor to spot these cars as instructed. If this cannot be accomplished, Trainmen will file a wire report addressed to Control Clerk, Ft. Madison upon their arrival at their outlying tie-uppoint. This report will only indicate the exceptions to the list furnished and also if any cars pulled from spot not so indicated by current orders.

Wire should also indicate times these activities occurred.

(2) If work done by Trainmen who tie-up at Ft. Madison, these Trainmen will inform Control Clerk at Ft. Madison of any and all work performed at the previously referred to Blind Sidings.

```
ZONE 8
                     Argyle Iowa
 CLIC NO.
                     NAME
 08 01 00
08 01 01
08 01 10
                     Argyle Iowa
                     Des moines Farm Sev. (Open)
                     Farmers Coop (Open)
                     ZONE 9
Revere Mo.
 CLIC NO.
                    NAME
 09 01 01
09 02 01
                    Revere Seed (Open)
Revere B/O Setouts
                        ZONE 10
                    Medill Mo.
CLIC NO.
                    NAME
10 01 00
10 02 01
                    Medill Siding Ball Fertz. (Chutes)
  thru 06
10 02 07
10 03 01
10 03 10
10 04 01
                    Ball Fertz. Ammo. Tnk.
                    Nachurs Plnt. Fd. (Open)
                    Heat Gas (Open)
                    BN Conn. (Log Ldg.)
                       ZONE 11
                  Wyaconda Mo.
CLIC NO.
                    NAME
                   MFA Exchge. Co. (Door)
MFA Exchge. Co. (Door)
Smith Bros. (Open)
Wyaconda Mach. (Ramp)
MFA Exchge. Co. (Door)
Smith Bros. (Doors)
11 01 01
11 01 02
11 02 01
11 03 01
11 03 10
11 03 20
 thru 23
11 03
11 03
                   Morgan Oil (Chute)
                   Morgan Oil (Chute)
                     ZONE 12
Gorin Mo.
CLIC NO.
                   NAME
12 01 01
                  Foss Grain (Doors)
thru 05
12 01 06
                   Foss Grain (Chute)
```

- C -

ZONE 12 CONT'D Gorin Mo. CLIC NO. NAME 12 01 10 12 02 00 Bunk Car Spot Runaround ZONE 13 Niota Ill. CLIC NO. NAME 13 01 01 Niota Elev. (Doors) thru 03

Niota Elev. (Tank)

NAME

NAME

Team Trk. Storage Trk.

ZONE 15 Lomax Ill.

13 01 04 13 02 01 13 03 00

CLIC NO.

14 01 01

14 02 01

14 03 01 14 04 00

CLIC NO.

15 01 01 15 01 10 15 02 00

15 03 00

Bunk Cars Spot (Open)

Storage Trk.

ZONE 14 Dallas City Ill.

Pioneer Lbr. (Open)

Cert. Rdy. Mix (Open)

Lomax Elev.
Lomax Team Trk. (Open)
Bunk & Co. Mtl. Stge.
Bunk & Co. Mtl.


- D -

#### INTRODUCTION

This booklet contains instructions and maps concerning the Santa Fe CAR LOCATION INVENTORY CONTROL (CLIC) System for Ft. Madison, Iowa.

Each track has been assigned a number to be referred to as the "CLIC" number.

This number consist of six digits. They are designated as the ZONE. TRACK and SPOT number as shown in the example below:



The following pages set forth the general instructions pertaining to Yardmasters. Switchmen and Trainmen.

Also contained within this booklet is both a numeric and alphabetic listing of all tracks and industries, indicating the CLIC number assigned to each.

As you will gather while reading these instructions, the key factor to the successful operation of the CLIC System is <u>COMMUNICATIONS</u>. The Yard-master must communicate with the Clerks and with the Switchmen. The Switchmen must communicate with the Yardmaster and the Clerks must communicate with the Yardmaster.

#### GENERAL INSTRUCTIONS

- (1) All switching in the yard and at industries will be performed using the switch lists furnished by Control Clerk unless otherwise instructed by Yard-master.
- (2) Disposition to be made of all cars will be shown on list opposite car number. This disposition will be so indicated by means of the CLIC number.
- (3) Yardmaster will indicate on each switch list where cuts, if any, are to be made, as follows:

1st Cut - - - - - - - etc.

- (4) Engine Foreman will switch cars according to list as marked by Yardmaster. Should engine foreman switch or place a car to some location other than the one marked on the list, he must promptly advise yardmaster as to the correct location.
- (5) Engine Foreman will promptly advise Yardmaster as to the disposition made of car or cars not shown on list.
- (6) Engine Foreman must notify Yardmaster immediately of any exceptions to the list, such as car not shown on list, cars not standing as listed, and car shown on list but not physically present.

### GENERAL INSTRUCTIONS (CONT'D)

- shown on foreman's list, Engine Foreman must either secure permission from the Yardmaster to perform such additional service or do the switching and, upon return to the yard, inform the Yardmaster as to the work completed. Yardmaster will, in turn, inform the Control Clerk of any and all extra switching performed. This must be done without fail in order that the Santa Fe be able to collect all charges due under prevailing Tariffs.
- (8) If a car other than the one ordered to an industry by the Yardmaster or Agent is spotted, the Engine Foreman must notify the Yardmaster of any substitutions, informing him as to which car was actually furnished.
- (9) Yardmaster should be aware of all switching performed in the yard and at industries and Engine Foreman must advise Yardmaster of any and all extra moves.

  (10) Yardmaster will be furnished four copies of switch list (818-B). After marking said list, Yardmaster will return original to Control Clerk except list pertaining to work performed at an industry. These will be returned when spotting and pull times are ascertained.

#### GENERAL INSTRUCTIONS (CONT'D)

- (11)Yardmaster will indicate the following items on each switch list:
  - a. Cut switched from East or West End of the Yard.
  - Engine Foreman's Name b.
  - Time switching started and time completed.
- (12) For observation and precaution, the following codes may be shown on switch list under "DEM INSTA" column preceding car initial:

BO - Bad Order

DN - Dangerous

HE - Head End Movement Only RE - Rear End Movement Only

PU - Car Partially Unloads

WH - Weigh Car

HB - Hold For Billing.

LL - Leased car on Leased Track
TT - Team Track Loading or Unloading.

(13) BAD ORDERS - Whenever Bad Order cars are switched out, Yardmaster must be immediately informed and he in turn must immediately inform the Control Clerk.

(14) The function of the Control Clerk in the Yard Office is to keep track of the location of every car in the Ft.

Madison area. In order to accomplish

moves in which a car either is switched

this. Yardmaster must advise him of all

within a track or moved from one location to another. Consequently, the Engine

Foremen must advise the Yardmaster of any and all exceptions.

#### ZONE 1

CLIC NO.	NAME
01 06 00 01 07 00 01 08 00 01 09 00 01 11 00 01 12 00 01 13 00 01 14 00 01 15 00 01 16 00 01 17 00 01 18 00 01 19 00 01 21 01 01 22 00 01 23 00 01 24 00 01 25 02 01 26 01 01 27 00 01 28 00 01 29 00 01 32 00 01 32 00 01 32 00 01 33 00 01 33 00 01 34 01 01 35 01 01 36 01	Yard Trk. 6 Yard Trk. 7 Yard Trk. 8 Yard Trk. 9 Yard Trk. 11 Yard Trk. 12 Yard Trk. 13 Yard Trk. 14 Yard Trk. 15 Yard Trk. 16 Yard Trk. 16 Yard Trk. 19 Yard Trk. 19 Yard Trk. 19 Yard Trk. 20 Rip Trk. Rip Drop Pit Rip Trk. Back Trk. Lead Anchor Metals Boyles Galv. Boyles Galv. Old Derrick Trk. Back Lead Scale Trk. West Scale Trk. East Turntable Trk. Turntable Trk. Stock Trk. Giffin Sawmill Piggy Back Ramp Sinclair Trk. Sinclair Trk.
	ZONE 2

# NAME

CFM Trk.

CLIC NO.

02 01 00

04 02

06 02

07

02 07 01 02 08 00

02 00

03 00

00

00

00

00

02

02

02 05

02

Coach 38 Trk. Stand By So. Eng Lead

Eng. Sand Trk. Sand Spot No. Eng. Lead

Freight Hse. Trk. Yard Lead

- 5 -

### ZONE 2 CONT'D

	ZONE 2 CONT'D
CLIC NO.	NAME
02 09 00 02 09 01 02 10 00 02 11 00 02 12 01 02 13 00 02 13 01 thru 05 02 14 00 02 14 01 thru 03 02 15 00 02 16 00 02 17 00 02 18 00 02 18 01 thru 03 02 19 00 02 20 00 02 21 00	Water Treat. Plnt. Trk. Water Treat. Spot RH Runaround Turntable Trk. Old Gasoline Spur Gasoline Spur Spot Oil Rack Oil Rack Spots  North Elev. Cert. Ready Mix  Spur Trk. South Elev. Old #10 Gleason Spur Gleason Corp. Spots  Old #10 Stub Trk. Chute 3
	ZONE 3
CLIC NO.	NAME
	<del></del>
03 01 01 03 02 01 03 02 02 03 03 01 thru 04 03 03 05 thru 08 03 04 00	Schaffer Pen Co. Crandon Ldg. Inside Crandon Ldg. Inside Crandon Dock Scrap Ppr. Crandon Chem. & Chips Runaround
03 02 01 03 02 02 03 03 01 thru 04 03 03 05 thru 08	Crandon Ldg. Inside Crandon Ldg. Inside Crandon Dock Scrap Ppr. Crandon Chem. & Chips
03 02 01 03 02 02 03 03 01 thru 04 03 03 05 thru 08	Crandon Ldg. Inside Crandon Ldg. Inside Crandon Dock Scrap Ppr. Crandon Chem. & Chips Runaround

## ZONE 4 CONTID

	ZONE 4 CONT.D
CLIC NO.	NAME
04 06 00 04 06 01 04 07 00 04 07 01 04 08 00 04 09 00 04 10 00 04 11 01 thru 03 04 11 09 thru 08 04 11 09 thru 12 04 12 00 04 12 01 04 12 01 04 12 07 04 13 00	North Lead Spot Piling Trk. Piling Trk. Spot Back Yard B Bark Yard C S/H Lead Storehouse Trk. S/H Dock  S/H Open Area S/H Dock  New Whl. Trk. New Whl. Trk. Open New Whl. Trk. Dock
ZONE 5 <b>Frue</b> hauf Plant	
CLIC NO.	NAME
05 01 00 05 01 01	
	ZONE 6
	Ortho Plant
CLIC NO.	NAME
06 01 00 06 02 00 06 03 00 06 04 00 06 05 00 06 06 00 06 07 00 06 08 00 06 09 00	Ortho Ortho Dely Ortho Dely Ortho Dely Ortho Receiving Ortho Receiving Ortho Dely Ortho Receiving Ortho Coly Ortho Receiving
•	ZONE 7 Armour Dial Plant
CLIC NO.	NAME
07 00 00	Armour Dial Lead
average and a second	• 7 =
	- / <del>-</del>

# ZONE 7 CONT'D

CLIC NO.	NAME		
07 01 00 07 02 00 07 03 01 thru 04 07 04 00	Armour Dial Armour Dial Armour Dial Doors		
07 04 00 07 05 00	Armour Dial Armour Dial		
07 06 00	Armour Dial		
07 07 00	Armour Dial		
07 08 31 thru 35	Armour Dial Doors		
thru 35 07 08 36	Armour Dial Dock		
thru 39	Almour Digi Dock		
07 09 01	Armour Dial Inside Open		
thru 05 07 10 01 thru 05	Armour Dial Inside Open		
	ZONE 8 Argyle Iowa		
ar ta vo			
CLIC NO.	NAME		
08 01 00 08 01 01 08 01 10	Argyle Iowa Des Moines Farm Sev.(Open) Farmers Coop (Open)		
	ZONE 9 Revere Mo.		
CLIC NO.	NA ME		
·			
09 01 01 09 02 01	Revere Seed (Open Area) Revere B/O Setouts		
	ZONE 10 Medill Mo.		
CLIC NO.	<u>na me</u>		
10 02 01	Medill Siding Ball Fertz, (Chutes)		
10 03 01 10 03 10	Ball Fertz, Amo. Tnk. Nachurs Plnt. Fd. (Open) Heat Gas (Open) BN Conn. (Log. Ldg.)		

ZONE 11 Wyaconda Mo. CLIC NO. NAME MFA Exchge. Co. (Door)
MFA Exchge. Co. (Door)
Smith Bros. (Open) 11 01 01 11 01 02 11 02 01 11 03 01 11 03 10 11 03 20 thru 23 Wyaconda Mach. (Ramp)
MFA Exchge. Co. (Door)
Smith Bros. (Doors) 30 Morgan Oil (Chute) Morgan Oil (Chute) 11 03 **11** 03 31 ZONE 12 Gorin Mo. CLIC NO. NA ME

Runaround

ZONE 13 Niota Ill.

NAME

Storage

NAME

Team

Storage

ZONE 14 Dallas City Ill.

12 01 01

12 01 06 **1**2 01 10 12 02 00

CLIC NO.

13 01 01

thru 03 13 01 04 13 02 01

13 03 00

CLIC NO.

14 01 01 14 02 01 14 03 01

14 04 00

thru 05

Foss Grain (Doors) Foss Grain (Chute) Bunk Car Spot

Niota Elev. (Doors) Niota Elev. (Tank) Bunk Cars Spot (Open)

9 -

Pioneer Lbr. (Open) Cert. Rdy. Mix (Open)

ZONE 15 Lomax Ill.

CLIC NO.	NAME_	
15 01 01 15 01 10 15 02 00	Lomax Elev. Lomax Team Trk. (Ope Bunk & Co. Mtl. Stge	m)


**Hane** CLIC NO. Anchor Metals 01 25 01 01 25 01 01 25 02 08 01 00 07 08 36 thru 39 07 00 00 07 01 00 07 02 00 07 03 01 thru 04 07 04 00 07 05 00 Anchor Netals Argyle Iowa Armour Dial Dock Armour Dial Lead Armour Dial Armour Dial Armour Dial Doors Armour Dial 07 04 00 07 05 00 07 06 00 07 07 00 07 08 31 Armour Dial Armour Dial Armour Dial Armour Dial Doors thru 35 07 09 01 thru 05 Armour Dial Inside Armour Dial Inside 07 10 01 thru 05 Back Track 01 23 00 01 28 00 04 08 00 Back Lead Back Yard "B" 04 09 00 10 02 01 thru 06 Back Yard "C" Ball Fertz. (Chutes) thru 06 10 02 07 10 04 01 04 04 20 04 03 00 04 02 00 01 26 01 01 26 02 12 01 10 Ball Ferts. Amo. Track BN Conn. (Log Idg.) B & B Spot BN ICD BN ICR Boyles Galv. Boyles Galv. Bunk Car Spot Bunk Car Spot 13 02 01 15 02 00 Bunk & Co. Mtl. Stge. 02 14 01 thru 03 Cert. Ready Mix Cert. Ready Mix (Open) 14 02 01 CFM Track 02 03 00 02 21 00 02 04 00 03 03 05 Chute three Coach 38 track Crandon Chem. & Chips thru 08 03 02 01 03 02 02 Crandon Idg. Inside Grandon Idg. Inside Crandon Dock Scrap Paper 03 03 01 thru 04


NAME Des Noines Farm Serv. (Open)	CLIC NO. 08 01 01
Engine Sand Track	02 07 00
Farmers Coop. (Open) Foss Grain (Doors)  Foss Grain (Chute) Four Hundred Lead Freight House Track Fruehauf Track Fruehauf Spot	08 01 10 12 01 01 thru 05 12 01 06 04 00 00 02 01 00 05 01 00 05 01 01
Gasoline Spur Spot Giffin Sawmill Gleason Corp. Gleason Spur	02 12 01 01 33 01 02 18 01 thru 03 . 02 18 00
Heat Gas (Open)	10 03 10
Lead Lead Track Lomax Elevator Lomax Team Track (open)	01 24 00 04 13 00 15 01 01 15 01 10
Medill Siding M F A Exchange Co. (Door) M F A Exchange Co. (Door) M F A Exchange Co. (Door) Morgan Oil (Chute) Morgan Oil (Chute)	10 01 00 11 01 01 11 01 02 11 03 10 11 03 30 11 03 31
Nachurs Plant Fd. New WHL Track New WHL Track (Open) New WHL Track (Dock) New WHL Track (WHLS) Niota Elevator (Door)	10 03 01 04 12 00 04 12 01 04 12 02 thru 06 04 12 07 13 01 01 thru 03
Niota Elevator (Tank) North Engine Lead North Elevator "N" Contd.	13 01 04 02 08 00 02 14 00
- 12 -	


HANE	CLIC NO.
North Lead Spot	04 06 00 04 06 01
Oil Rack Spots	02 13 00 02 13 01 thru 05
Old Derrick Track Old Gasoline Spur Old No. 10 Old No. 10 Old No. 10 Ortho Ortho Dely. Track Ortho Dely. Track Ortho Dely. Track Ortho Recv. Track Ortho Recv. Track Ortho Delv. Track Ortho Recv. Track Ortho Recv. Track Ortho Delv. Track	01 27 00 02 12 00 02 17 00 02 19 00 04 04 00 06 01 00 06 02 00 06 03 00 06 04 00 06 05 00 06 06 00 06 07 00 06 08 00 06 09 00
Phillipps Feinberg Piggy Back Ramp Piggy Back Ramp Piling Track Piling Track Spot Piomeer lumber (Open)	04 04 01 01 34 00 01 34 01 04 07 00 04 07 01 14 01 01
Revere Badorder Set outs Revere Seed (Open) Roundhouse Runaround Rip Drop Pit Rip Track Rip Track Runaround Runaround	09 02 01 09 01 01 02 10 00 01 21 01 01 21 00 01 22 00 03 04 00 12 02 00
Scale Track Sand Spot Schaffer Pen Co. S/H Open area S/H Dook	01 29 00 02 07 01 03 01 01 04 11 04 thru 08 04 11 09
S/H Dock S/H Lead Sinclair Track	thru 12 04 11 01 thru 03 04 10 00 01 35 01
Sinclair Track "S" Contd.	01 36 01


NAME CLIC NO. Smith Bros. (Open) Smith Bros. (Doors) 11 02 01 11 03 20 thru 23 02 16 00 02 06 00 South Elevator South Engine Lead 02 06 00 02 15 00 02 05 00 01 33 00 13 03 00 14 04 00 04 11 00 02 20 00 Spur Track Stand Bye Stock Track Storage Track Storage Track Storehouse Track Stub Track Team Track 14 03 01 04 04 10 04 05 00 04 05 01 Team Unldg Test Car Track Test Car Track Spot Turn table Track Turn table Track 01 31 00 01 32 00 02 11 00 Turn table Track Water Treat Plant Track 02 09 00 Water Treat Plant Track 02 09 01 Wye Track 04 01 00 Wyoconda Mach. (Ramp) 11 03 01 Yard Lead 02 02 00 Yard Track 6 Yard Track 7 01 06 00 01 07 00 01 08 00 Yard Track 8 Yard Track 9 Yard Track 11 Yard Track 12 01 09 00 01 11 00 01 12 00 01 13 00 Yard Track 13 Yard Track 14 Yard Track 15 Yard Track 16 01 14 00 01 15 00 01 16 00 Yard Track 17 Yard Track 18 Yard Track 19 01 17 00 01 18 00 01 19 00 01 20 00 Yard Track 20


- II -





















-To Konsos CITY TO CHICAGO P. 8 ZONE 5 WESTBOUND MAIN -EASTBOUND MAIN OPEN FRUEHAUF CORPORATION








PIZ ZONE 9 901 Ol Open Area
REVERE SEED & SUPPLY Open Area WESTWARD MAINT -- TO KANSAS CITY EASTWARD MAIN T TO CHICAGO 902 Open Area BAO- ORDER REVERE, MISSOURI





ZONE 12 Open 1201 DA-BUNE CAR SET POSS GRAIN MASTNARD MAINT ERSTWARD MAN To Guenso 1 GORIN, MISSOURI

