KEEP THE SAFETY HABIT



CAR LOCATION INVENTORY CONTROL

INSTRUCTIONS MAPS.
INDUSTRIAL ZONE, TRACK,
SPOT NUMBERS

CLOVIS

NEW MEXICO DIVISION

NUMBER 5 ISSUE JUNE I, 1980 INSTRUCTIONS SET FORTH BELOW GOVERN THE OPERATION OF CAR LOCATION INVEN-TORY CONTROL (CLIC). THIS DIVISION IS DIVIDED INTO ZONES WITH EACH ZONE HAVING DESIGNATED TRACKS AND/OR IND-

USTRIES WITHIN ITS BOUNDRIES. TRACKS ARE ASSIGNED SPECIFIC NUMBERS WITHIN THE ZONES AND SPSOTS ON THE TRACKS

ARE GIVEN INDIVIDUAL NUMBERS. BY US-ING ZONE, TRACK AND SPSOT NUMBERS, WE ARE ABLE TO PRINT SWITCH LISTS WHICH WILL REFLECT THE LOCATION TO WHICH A CAR SHOULD BE SPOTTED.

A CLIC SPOT NUMBER WILL CONSIST OF SIX DIGITS: THE FIRST TWO DIGITS DESIGNATE THE ZONE TO WHICH A CAR IS DESTINED; THE SECOND TWO DIGITS INDICATE THE TRACK NUMBER WITHIN THE ZONE; THE LAST TWO DIGITS REPRESENT THE ACTUAL SPOT ALONG THE TRACK.

> EXAMPLE OF CLIC SPOT NUMBER

67 25 01 LANCASTER WHOLESALE ' '--- SPOT NUMBER '----TRACK NUMBER ----ZONE NUMBER

ALL INDUSTRIES WILL BE REFERRED TO BY CLIC SPOT NUMBER RATHER THAN BY NAME.

SWITCHES ARE PAINTED WITH ZONE AND TRACK NUMBER SHOWN ON EITHER TARGET OR STAND. SPOT NUMBERS HAVE BEEN PAINTED ON DOORS, DOCKS, BUILDINGS, GATES, ETC WHERE POSSIBLE; OTHERWISE, THE PROPER SPOT CAN BE DETERMINED BY NOTING SPOT DESCRIPTIONS THAT ARE FOUND JUST OPPO-

SITE ZONE MAPS ON THE FOLLOWING PAGES

THE MAPS ARE NOT DRAWN TO SCALE, BUT MERELY SERVE AS A GUIDE IN LOCATING PROPER TRACKS OR SPOTS.

OF THIS BOOK.

THE FOLLOWING INSTRUCTIONS PERTAIN SPECIFICALLY TO THE PHYSICAL SWITCH ING. SPOTTING AND PULLING OF CARS ARE CALLED PARTICULARLY TO THE ATTENTION OF ALL TRAINMEN FOR THEIR COMPLIANCE:

(1) ALL SWITCHING WILL BE PERFORMED BY USE OF SWITCHLIST UNLESS OTHER-WISE INSTRUCTED.

(2) DISPOSITION TO BE MADE OF CAR WILL BE SHOWN ON SWITCH LIST UNDER CLIC NO. INDUSTRY TO.

(3) CONDUCTOR/ENGINE FOREMAN WILL SWITCH CARS ACCORDING TO LIST. SHOULD IT BE NECESSARY FOR CONDUCTOR ENGINE FOREMAN TO SWITCH OR PLACE TO SOME LOCATION OTHER THAN DESTINATION SHOWN ON SWITCH LIST, HE MUST SO INDICATE ON SWITCH LIST.

(4) IF CAR IS NOT ACTUALLY SPOTTED, BUT LEFT ON THAT INDUSTRY'S TRACK, THE CONDUCTOR WILL INDICATE (ON TRACK NOT PLACED) IN THE FOLLOWING MANNER, (OTNP). IF CAR IS PLACED ON TRACK OR SOME OTHER TRACK, FOR SWITCHING CONVENIENCE, CONDUCTOR WILL INDICATE ON LIST (ON TRACK CARRIERS CONVENIENCE) IN THE FOLLOWING MANNER, (OTCC)

(S) CONDUCTOR MUST MAKE NOTATION ON SWITCH LIST OF ANY EXCEPTIONS TAKEN TO SWITCH LIST, SUCH AS NO CAR, CAR NOT ON LIST, CAR OUT OF LINE, CAR IS HAZARDOUS, EXCESS DIMENSION (WHEN THE INFORMATION IS NOT SO INDICATED ON SWITCH LIST), CAR IS CARDED REAR OR HEAD END MOVEMENT ONLY, OR ANY OTHER EXCEPTIONS NOTED.

(6) NOTATION MUST BE MADE INDICATING ANY EXTRA SWITCHING MOVES MADE WHICH ARE NOT SHOWN ON SWITCH LIST.

(7) IF A CAR OTHER THAN ONE ORDERED TO AN INDUSTRY IS SPOTTED, CONDUCTOR ENGINE FOREMAN MUST INDICATE ON LIST CAR NUMBER ACTUALLY SPOTTED.

(8) CONDUCTOR/ENGINE FOREMAN MUST SHOW ON SWITCH LIST ACTUAL TIME CAR ARE PLACED OR PULLED AT AN INDUSTRY.

(9) CONDUCTOR/ENGINE FOREMAN WILL INDICATE ON SWITCH LIST ANY WORK NOT COMPLETED, SHOWING TIME AND DATE AL_L SWITCHING ON LIST IS COMPLETED, SIGN HIS NAME IN FULL AND RETURN SWITCH LIST TO ISSUING AGENCY FOR PROCESSING. ICC SERVICE DIRECTIVE EX-PARTE 285 REQUIRES A LIST OF CARS SPOTTED OR PULLED FROM AN INDUSTRY INDICATING: CAR INITIAL AND NUMBER (B) WHETHER LOADED OR EMPTY (C) WHETHER SPOTTED OR PULLED (D)TIME, DATE, ENGINE OR TRAIN NUMBER, AND-(E) OF CONDUCTOR/ENGINE SIGNATURE FOREMAN PERFORMING THE SWITCHING. EACH CONDUCTOR/ENGINE FOREMAN MUST FURNISH THE SIGNED LIST TO AGENCY THAT MAINTAINS RECORDS OF SUCH CARS. £ 403 IF AN INDUSTRY REQUESTS SERVICE NOT SHOWN ON SWITCH LIST, CONDUCTOR/ ENGINE FOREMAN SHOULD OBTAIN SUCH IN WRITING. REQUEST THIS REQUEST TO BE TURNED IN WITH SWITCH LIST FOR PROCESSING. IF UNABLE TO OBTAIN RE-IN URITING, CONDUCTOR/ENGINE FOREMAN SHOULD RECORD ON SWITCH LIST THE NAME OF PERSON MAKING REQUEST, THE SERVICE REQUESTED AND PERFORMED. BE SHOWN ON SWITCH 81 BAD ORDER

FOR OBSERVATION AND GUIDANCE, THE FOLLOWING CODES MAY LIST PRECEDING THE CAR INITIAL.

C1 CONDEMNED CAR CB COMBUSTIBLE (HAZARDOUS) CL CHLORINE (HAZARDOUS) CM CORROSIVE (HAZARDOUS)

CU COMPLETELY UNLOADS DG **DANGEROUS** (HAZARDOUS) EP EMPTY PLACED OR TO PLACE LOADING FG FLAMMABLE GAS (HAZARDOUS)

FH FLAMMABLE GAS (HAZARDOUS) FL FLAMMABLE (HAZARDOUS) FS FLAMMABLE SOLID (HAZARDOUS)

HB HOLD FOR BILLING HC FOR CHARGES OR PERMIT HOLD FOR DISPOSITION HD HOLD HE HEAD END MOVEMENT

INTERPLANT SWITCH

SHIPPERS ORDER NOTIFY CAR

HS

IPSW

HOLD

SWITCHING CODES CONTINUED FROM PRE-VIOUS PAGE (C)

NG - NONFLAMMABLE GAS (HAZARDOUS)
OM - OXIDIZER (HAZARDOUS)

OP - ORGANIC PEROXIDE (HAZARDOUS)
OTCC ON TRACK CARRIERS CONVENIENCE

OTNP ON TRACK NOT PLACED
OX - OXYGEN (HAZARDOUS)

OX - OXYGEN (HAZARDOUS)
PA - POISON GAS (HAZARDOUS)
PB - POISON (HAZARDOUS)

(HAZARDOUS)

PU - CAR PARTIALLY UNLOADS
RE - REAR END MOVEMENT ONLY

REJT CAR REJECTED BY SHIPPER RELD UNLOADED AND BEING RELOADED RSPT RESPOT DUE TO RAILROAD ERROR

TT - TEAM TRACK LOAD
TURN TURN CAR AND RESPOT

WH - WEIGH HEAVY WL - WEIGH LIGHT XA - EXPLOSIVES A (HAZARDOUS)

EXPLOSIVES R

XX - DO NOT MOVE

XB -

GOOD COMMUNICATION AND COMPLIANCE

THIS CAR

WITH INSTRUCTIONS IS ESSENTIAL FOR A COMPLETE AND SUCCESSFUL CLIC OPERATION. YOUR REPORTINGS ARE THE KEY TO ACCURATE RECORDS.

THE COMPLETE COOPERATION OF EVERY EMPLOYE IS SOLICITED.


TRAINMASTER'S INSTRUCTIONS NO. 72 Clovis, March 13, 1974

YARDMASTERS AND ENGINE FOREMEN - CLOVIS


Effective at once when placing cars to industries "CLIC" switch lists (Form 818B Std.) should be marked showing actual placement time. This includes both empties spotted for loading and loads placed for unloading. As soon as engine foreman has access to radio or talk-back, he must notify yardmaster of the time car spotted. Yardmaster will then immediately notify "CLIC" Clerk of the placement time so that reports can be made. It will also be necessary to show on engine foreman's list cars placed on industry track even though not spotted and this information must be relayed to yardmaster immediately.

See no failure to comply with these instructions.


```
Yard Track Number 9 and North Lead
0109
         Middle Lead and Round House Lead
0119
         Garrett Spur - Curry County Grain
0161
        A & B Farm Supply, Tank Unloading Spot
0161 01
       A & B Farm Supply, Tank Unloading Spot
0161 02
0161 03
       A & B Farm Supply, Tank Unloading Spot
        A & B Farm Supply, Tank Unloading Spot
0161 04
0161 05
        A & B Farm Supply, Tank Unloading Spot
        Curry County Grain, Unloading Pit & Loading Spout
0161 21
0161 31 Curry County Grain, Fertilizer Tanks
         Cleaning Track, Mechanical Dept., WE Yards
0171
        West Bound Main
0198
         East Bound Main
0199
```




	10 0 1		
0103	Yard Track 3	0141 0	1 ElRancho Milling, Open Area EE of Track
0104	Yard Track 4	0141 0	The state of the s
0105	Yard Track 5	0141 0	
0106	Yard Track 6	0141 0	
0107	Yard Track 7	0141 0	The state of the s
0108	Yard Track 8	0141 0	Lie Vacol
0109	Yard Track 9 and North Lead	0141 0	
0110	Yard Track 10	0141 0	manufacture in the state of the
0111	Yard Track 11	0141 0	
0112	Yard Track 12	0141 10	=======================================
0113	Yard Track 13	0141 1	
0114	Yard Track 14		The state of the s
0115	Yard Track 15	0141 12	werner when were were of ping.
0116	Yard Track 16	0141 13	manufacture with the manufacture of the manufacture
0117	Yard Track 17	0141 14	per ment blug.
0118	Roundhouse One Track	0197	Harvey Track
0110	Roundhouse Lead & Middle Lead	0198	West Bound Main
0110	South Lead	0199	East Bound Main
		0324	Lead to Zone 3 (Sand Hills)
0121	Scale Track	0447	Lead to Zone 4 (Rip Area)
0122	Storage Track Number 1	0601	Lead to Zone 6 (Carlsbad District)
0123	Storage Track Number 2	0602	West Leg of Wye
0124	Storage Track Number 3		
	15	L N	
		[2] Z	
•	OF	u	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
	THORNTON	HINKLE	HARVEY L
	0131	 	OISO REA DEPOT HOUSE
			0197 0130 0198
			Q199 Q103
	T. 80, 001		0104
<u>•₩</u> • 7	76 BELEN	0106	TO AMARILLO - E -
		0107	
		0108	
		0109	
		0111 0112	
		0113	
		0114 0115	
		0116 0117	0/16
0119		<u> </u>	
0122	SCALE TRACK	©	Yo. OFF.
<u>0/23</u> <u>0/24</u>			
			3
	- N	TURN 5	ZONE 1
	83	TABLE -	
			····




```
Yard Track Number 3
0103
         Yard Track Number 4
0104
0105
         Yard Track Number 5
         Yard Track Number 6
0106
0107
         Yard Track Number 7
         Yard Track Number 8
0108
0109
         Yard Track Number 9
                               and Nine Pocket
         Yard Track Number 10
0110
0111
         Yard Track Number 11
         Yard Track Number 12
0112
0113
         Yard Track Number 13
         Yard Track Number 14
0114
0115
         Yard Track Number 15
0116
         Yard Track Number 16
         Yard Track Number 17
0117
         Round House Lead
0119
         Safeway Milk Plant
0182 01
         Harvey Track
0197
0198
         West Bound Main
```




0201 0202 0203 0204 0205 0206 0207 0208 0219	Roundhouse Service Track 1 Roundhouse Service Track 2 Roundhouse Service Track 3 Roundhouse Service Track 4 Roundhouse Service Track 5 Roundhouse Service Track 6 Lube Oil Track L U G Track off of Turntable Roundhouse Lead Pass Thru. Track	0222 North Caboose Track 0223 Slaton Caboose Track 0224 Pool Caboose Track 0225 Roundhouse Tail Track 0231 Griffith Spur 0241 High Line Track 0241 01 Sand House Spot at WE of Track 0241 02 Sand House Spot 0241 03 Sand House Spot
		0243 01 Diesel Oil Spur 0243 02 0243 03 0243 04 0314 Wafer Service Track (See Zone 3)




0204	Roundhouse Service Track 4
0205	Roundhouse Service Track 5
0206	Roundhouse Service Track 6
0219	Roundhouse Lead
0231 0232	Griffith Spur
0232	Power House Lead
\perp_{0221}	Pass Thru Track
0241	High Line Track
0318	Lead to Sand Hill Area (See Zone 3)





0124	Storage Track Number 3 (See Zone 1)
0311	Torres Spur Number 1
0312	Torres Spur Number 2
0313	Torres Spur Number 3
0314	Water Service Track
0315	North B & B Track
0316	South B & B Track
0318	Yard Track Number 18
0319	Yard Track Number 19
0320	Yard Track Number 20
0321	Yard Track Number 21
0322	Yard Track Number 22
0323	Yard Track Number 23
0324	Yard Track Number 24
0447	Lead to Rip Track Area (See Zone 4)



```
Roundhouse Lead (See Zone 2)
0219
0318
         Yard Track Number 18
         Yard Track Number 19
0319
0320
         Yard Track Number 20
         Yard Track Number 21
0321
0322
         Yard Track Number 22
0323
         Yard Track Number 23
         Yard Track Number 24
0324
0407
         Long Bell Spur (See Zone 4)
         Steel Spur (See Zone 4)
0416
0437
         Lead to Rip Track Area (See Zone 4)
```










0406 01 Feed & Runch, Door 1 0406 02 Feed & Ranch, Door 2 0406 03 Feed & Ranch, Door 3 0406 04 Feed & Ranch, Spot 4 0406 05 Feed & Ranch, Spot 5 0406 06 Feed & Ranch, Winch Spot 0407 01 Long Bell. South Door 0407 02 Long Bell, Middle Door 0407 03 Long Bell. North Door 0407 04 American Metals, Open Area 0407 09 Houston Lbr. Co., Open Area 0416 Steel Spur 0417 01 Worleys, Molasses Unloading 0417 02 Worleys, Open Area 0417 03 Worleys, Unldg Pit 0417 04 Worleys, Unldg Spout 0417 05 Worleys, Open Area 0417 06 Worleys, North Door 0417 07 Worleys, Middle Door 0417 08 Worleys, South Door (Sk Feed) 0418 01 C&T Fertz., Ammonia Tank NE

0418 02 C&T Fertz., Open Area 0418 03 C&T Fertz., Unld Pit 0418 04 C&T Fertz., Open Area 0418 05 C&T Fertz., Tank SE Rip Track 28 0428 0430 Rip Track 30 0431 Rip Track 31 Rip Track 32 0432 0433 Rip Track 33 0434 Rip Track 34 0435 Rip Track 35 0436 Rip Track 36 0437 Rip Track 37 0438 11 DSK Track, Open Area 0438 14 DSK Bldg., Unldg Dock 0471 03 Purina, Open Area 0438 15 DSK Track, Wheel Spot 0471 04 Purina, South Door 0438 16 DSK Track, Wheel Spot 0471 05 Purina, Middle Door 0438 18 DSK Car Oil Unld Spot 0471 06 Purina, North Door 0438 19 DSK No. 1 Diesel Oil 10471 07 Purina. Unldg Spout 0440 Tank Track

0442 Heavy Rip 2 0443 Heavy Rip 3 0444 Heavy Rip 4 0445 Heavy Rip 5 0446 Heavy Rip 6 0447 Heavy Rip 7 North One Spot Trk 0449 0450 South One Spot Trk 0451 Wheel Track 0461 MTC Repair Track North TOFC Track 0462 0463 South TOFC Track 0471 01 Purina. Open Area SE 0471 02 Purina, Open Area 0471 08 Purina. Open Area NE









```
East Leg of Wye
0601
         West Leg of Wye
0602
         Stock Pens Track
0603
        Taylor Evans - Gate
0603 01
0603 02 Taylor Evans - Tank Spout
0603 03 Taylor Evans - Tank Spout
0603 05 Stock Pens, North Chute
0603 06 Stock Pens. Middle Chute
0603 07 Stock Pens, South Chute
0603 08 Stock Pens, Hay Barn
0606 01 Tri State Industries, Open Area
0611 01 Wilbur Ellis - South Door
0611 02 Wilbur Ellis - Unloading Pit
0611 03 Wilbur Ellis - Open Area
0611 04 Wilbur Ellis - Open Area
0611 05 Wilbur Ellis - Open Area
```

O616 Swift Run A Round Track
O617 Swift & Co., North Track
O671 OO Swift & Co., Mtc. Ldg.
O617 O1 Swift & Co., Door Number 1
O617 O2 Swift & Co., Door Number 2
O617 O3 Swift & Co., Door Number 3
O618 Swift & Co., South Track
O618 O1 Swift & Co., Spot A, Tankage Ldg.
O618 O2 Swift & Co., Spot B, Hide Ldg. Door
O618 O3 Swift & Co., Spot C, Tallow Tank Ldg.
O618 O4 Swift & Co., Spot D, Hide Ldg. Dock
O618 O5 Swift & Co., Open Area West of Bldg.





East Track CAFB (All at Open Dock)
The line Dock at South End Bldg. 00302
Uncline Dock at South End Bldg. 00302
Uncline Dock Area between Bldgs 302 & 305.
Upon Dock Area between Bldgs 302 & 305.
Uncline Dock Area between Bldgs 302 & 305.

